







Number	Date	Modification	E	Owner
500000430021	31/07/2019			SUELLEKR




SECCAO "BB"
"BB" SECTION




SECCAO "AA"
"AA" SECTION



DETALHE "X"
"X" DETAIL
Scale 1:4



SECCAO "CC"
"CC" SECTION
Scale 1:2



DETALHE "C"
"C" DETAIL
Scale 1:2

0011	99010206	4 UN
0010	11537959	1 UN
0009	50322011	1 UN
0008	11537996	1 UN
0007	99030008	4 UN
0006	BZ194	4 UN
0005	BZ22525	6 UN
0004	50313796	1 UN
0003	50322012	1 UN
0002	10143038	2 UN
0001	99040042	4 UN
ITEM	CODE	QTY

PACOTE AUDACE LS NAO_TEM
LS AUDACE KIT
PAQUETE AUDACE LS

VERSÃO ATUAL
VERSION
VERSION

PADRÃO CLIENTE NAO_TEM
CUSTOMER STANDARD
PADRON CLIENTE

TRATAMENTO FILHOS: TS_04
SON TREATMENT
TRATAMIENTO HIJOS

TRATAMENTO SUPERFICIAL: NAO_TEM
SURFACE TREATMENT
TRATAMIENTO SUPERFICIAL

ESTRUTURA PORTINHOLA: TUBO_ALUMINIO
HINGED DOOR STRUCTURE
ESTRUCTURA PORTEZUELA

VAO LARGURA PORTINHOLA: 815,000
HINGED DOOR WIDTH OPENING
ABERTURA ANCHURA PORTEZUELA

TRAVAMENTO PORT INSPECAO LAT NAO_TEM
SIDE INSPECTION FLAP LOCKING
TRABAMIENTO PORT INSPECCIÓN LAT

MODELO DO CHASSI K_280_UB4X2LB_EURO_VI
CHASSIS MODEL
MODELO DEL CHASIS

CLP MODELO DE CARROCERIA TORINO
BODY MODEL CLP
CLP MODELO CARROCERÍA

LADO: DIREITO
SIDE
LADO

COLAR CONTORNO COM ADESIVO ACRÍLICO
TO PASTE OUTLINE WITH ACRYLIC ADHESIVE
E CENTRO COM SELANTE PU.
AND CENTER WITH PU SEALANT.
EXCEÇÕES SERÃO INFORMADAS
EXCEPTIONS WILL BE REPORTED
EM DESCRITIVOS OPERACIONAIS
IN PROCESS SHETT

	Scale: 1:7.5	Date: 31/07/2019	Denomination: PORTINHOLA FILTRO DE AR / INSPEÇÃO INSPECTION/ AIR FILTER FLAP PORTAZUELAS FILTRO DE AIRE /INSPECCIÓN
	View System: 	Liquid weight(Kg): 4,646	
	Origin: 11429877		
	Version: AA		
Project Office: ENO_MPIO	Use:	Code: 11537958	
Reviser by SAP WorkFlow VIEW IN PLM SYSTEM		Class: 506507	
Drawer SUELLEKR			